

dioxide, aliphatic aldehydes, rosin acids, terpenes, polycyclic aromatic hydrocarbons and organic acids.

Hazardous Polymerisation

NAP

Section VIII - Preventive measures - Personal protective equipment

Respiratory Protection

Not applicable for product in purchased form. A NIOSH/MSHA approved mask is recommended when the allowable exposure limits may be exceeded. Example: during cutting or sanding the product.

Hand protection

Not required. Cloth, canvas, or leather gloves are recommended.

Eye protection

Not applicable for product in purchased form. Safety glasses are recommended for machining the product.

Body protection

Not applicable for product in purchased form. Outer garments maybe desirable when machining.

Work/Hygienic Practices

If sanding or cutting the product follows good hygienic and housekeeping practices. Clean up areas where dust settles to avoid excessive accumulation of this combustible material. Minimize blowdown or other practices which blowdown or other practices which generate high airborne dust concentration.

GENERALLY APPLICABLE CONTROL MEASURES

Local Exhaust

If sanding or cutting the product: provide local exhaust as needed so that exposure limits are met.